

Table ENG-6. - Sanitary Facilities

Shenandoah County, Virginia

The information in this table indicates the dominant soil condition, but does not eliminate the need for onsite investigation. The numbers in the value column range from 0.01 to 1.00. The larger the value, the greater the potential limitation. Limiting features in this report are limited to the top 5 limitations. Additional limitations may exist.

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
1B: Alonzville	75	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
1C: Alonzville	85	Somewhat limited Too clayey Slope	0.50 0.37	Somewhat limited Slope	0.37	Somewhat limited Too clayey Slope	0.50 0.37
2B: Berks	80	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Gravel content Seepage	1.00 1.00 0.21
3C: Berks	55	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.37	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.37	Very limited Depth to bedrock Gravel content Slope	1.00 1.00 0.37
Weikert	35	Very limited Depth to bedrock Seepage Slope	1.00 1.00 0.37	Very limited Depth to bedrock Slope	1.00 0.37	Very limited Depth to bedrock Gravel content Seepage	1.00 1.00 0.50
4B: Blairton	75	Very limited Depth to saturated zone Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone Depth to bedrock	1.00 1.00	Very limited Depth to bedrock Depth to saturated zone Too clayey	1.00 0.96 0.50
4C: Blairton	75	Very limited Depth to saturated zone Depth to bedrock Too clayey	1.00 1.00 0.50	Very limited Depth to saturated zone Depth to bedrock Slope	1.00 1.00 0.37	Very limited Depth to bedrock Depth to saturated zone Too clayey	1.00 0.96 0.50
5B: Braddock	75	Very limited Seepage Too clayey	1.00 0.50	Very limited Seepage	1.00	Somewhat limited Gravel content Too clayey Seepage	0.78 0.50 0.21

5C:

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
5C:							
Braddock	75	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Gravel content	0.78
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
		Slope	0.37			Slope	0.37
6B:							
Braddock	75	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Content of large stones	0.87
		Content of large stones	0.87			Too clayey	0.50
		Too clayey	0.50			Gravel content	0.23
6C:							
Braddock	75	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Content of large stones	0.87
		Content of large stones	0.87	Slope	0.37	Too clayey	0.50
		Too clayey	0.50			Slope	0.37
6D:							
Braddock	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Content of large stones	0.87
		Content of large stones	0.87			Too clayey	0.50
7A:							
Broadway	80	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Flooding	1.00	Too clayey	0.50
		Seepage	1.00				
		Too clayey	0.50				
8B:							
Carbo	75	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
8C:							
Carbo	75	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
		Slope	0.37	Slope	0.37	Slope	0.37
9C:							
Carbo	50	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
		Slope	0.04	Slope	0.04	Slope	0.04

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
9C:							
Endcav	40	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Slope	0.04	Too clayey	1.00
		Too clayey	1.00	Depth to bedrock	0.01	Slope	0.04
		Slope	0.04			Depth to bedrock	0.01
9D:							
Carbo	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
Endcav	40	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.01	Too clayey	1.00
		Too clayey	1.00			Depth to bedrock	0.01
10A:							
Caverns	75	Very limited		Very limited		Somewhat limited	
		Seepage	1.00	Seepage	1.00	Seepage	0.50
		Flooding	0.40	Flooding	0.40		
11B:							
Chilhowie	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
						Gravel content	0.13
11C:							
Chilhowie	85	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
		Slope	0.37	Slope	0.37	Slope	0.37
11D:							
Chilhowie	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
11E:							
Chilhowie	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
12C:							

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
12C:							
Chilhowie	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
		Slope	0.37	Slope	0.37	Slope	0.37
12D:							
Chilhowie	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
13C:							
Chilhowie	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
		Slope	0.37	Slope	0.37	Slope	0.37
13D:							
Chilhowie	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
13E:							
Chilhowie	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
14B:							
Coursey	80	Very limited		Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50			Depth to saturated zone	0.47
Purdy	5	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
14C:							
Coursey	80	Very limited		Very limited		Somewhat limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Too clayey	0.50	Slope	0.37	Depth to saturated zone	0.47
		Slope	0.37			Slope	0.37

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
14C:							
Purdy	5	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
15A:							
Derroc	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Seepage	1.00
		Seepage	1.00	Seepage	1.00	Content of large stones	0.96
		Too Sandy	1.00			Too Sandy	0.50
16B:							
Edom	90	Very limited		Not limited		Very limited	
		Depth to bedrock	1.00			Too clayey	1.00
		Too clayey	1.00			Gravel content	0.05
16C:							
Edom	90	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Slope	0.37	Too clayey	1.00
		Too clayey	1.00			Slope	0.37
		Slope	0.37			Gravel content	0.05
17B:							
Endcav	90	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.01	Too clayey	1.00
		Too clayey	1.00			Depth to bedrock	0.01
17C:							
Endcav	75	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Slope	0.37	Too clayey	1.00
		Too clayey	1.00	Depth to bedrock	0.01	Slope	0.37
		Slope	0.37			Depth to bedrock	0.01
17D:							
Endcav	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Depth to bedrock	0.01	Too clayey	1.00
		Too clayey	1.00			Depth to bedrock	0.01
18B:							
Endcav	80	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	0.01	Too clayey	1.00
		Too clayey	1.00			Depth to bedrock	0.01
18C:							

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
18C:							
Endcav	80	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Slope	0.37	Too clayey	1.00
		Too clayey	1.00	Depth to bedrock	0.01	Slope	0.37
		Slope	0.37			Depth to bedrock	0.01
19D:							
Frederick	85	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
20B:							
Frederick	45	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
Poplimento	30	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
20C:							
Frederick	45	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
Poplimento	30	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
20D:							
Frederick	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
Poplimento	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
21B:							
Frederick	45	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
Poplimento	30	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
21C:							
Frederick	45	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
21C:							
Poplimento	30	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
21D:							
Frederick	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
Poplimento	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
21E:							
Frederick	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
Poplimento	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
22B:							
Frederick	45	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
Poplimento	30	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
22C:							
Frederick	45	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
Poplimento	30	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Slope	0.37			Slope	0.37
22D:							
Frederick	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
Poplimento	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00

23C:

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
23C:							
Frederick	45	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.04	Too clayey	1.00
		Slope	0.04			Slope	0.04
Poplimento	30	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.04	Too clayey	1.00
		Slope	0.04			Slope	0.04
23D:							
Frederick	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
Poplimento	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
24B:							
Gainesboro	45	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.95
		Too clayey	0.50			Too clayey	0.50
Berks	40	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
						Seepage	0.21
24C:							
Gainesboro	45	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.95
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
Berks	40	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
		Slope	0.37	Slope	0.37	Slope	0.37
24D:							
Gainesboro	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.95
Berks	40	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
24E:							
Gainesboro	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.95
Berks	40	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
25B:							
Gilpin	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
						Gravel content	0.62
25C:							
Gilpin	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	0.37	Slope	0.37	Gravel content	0.62
						Slope	0.37
25D:							
Gilpin	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
						Gravel content	0.62
26C:							
Gilpin	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	0.04	Slope	0.04	Gravel content	0.62
						Slope	0.04
26D:							
Gilpin	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
						Gravel content	0.62
27C:							
Gilpin	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	0.37	Slope	0.37	Gravel content	0.62
						Slope	0.37
27D:							

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
27D:							
Gilpin	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
						Gravel content	0.62
27E:							
Gilpin	90	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
						Gravel content	0.62
28C:							
Gilpin	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Slope	0.04	Slope	0.04	Gravel content	0.62
						Slope	0.04
28D:							
Gilpin	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
						Gravel content	0.62
28E:							
Gilpin	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
						Gravel content	0.62
29A:							
Gladehill	80	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Flooding	1.00	Seepage	0.50
		Seepage	1.00	Seepage	1.00		
30A:							
Guyan	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	0.50	Flooding	0.40	Too clayey	0.50
		Flooding	0.40				
Purdy	5	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
31B:							

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
31B:							
Jefferson	75	Very limited Seepage	1.00	Very limited Seepage	1.00	Somewhat limited Seepage Gravel content	0.50 0.42
31C:							
Jefferson	75	Very limited Seepage Slope	1.00 0.37	Very limited Seepage Slope	1.00 0.37	Somewhat limited Seepage Gravel content Slope	0.50 0.42 0.37
32C:							
Jefferson	75	Very limited Seepage Slope	1.00 0.04	Very limited Seepage Slope	1.00 0.04	Somewhat limited Seepage Gravel content Slope	0.50 0.42 0.04
32D:							
Jefferson	75	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage Gravel content	1.00 0.50 0.42
33C:							
Jefferson	75	Very limited Seepage Slope	1.00 0.16	Very limited Seepage Slope	1.00 0.16	Somewhat limited Seepage Gravel content Slope	0.50 0.42 0.16
33D:							
Jefferson	75	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage Gravel content	1.00 0.50 0.42
33E:							
Jefferson	75	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage Gravel content	1.00 0.50 0.42
34B:							
Laidig	75	Very limited Depth to saturated zone Depth to thick cemented pan	1.00 1.00	Very limited Depth to cemented pan Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Depth to cemented pan Seepage Gravel content	1.00 0.21 0.06
34C:							

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
34C:							
Laidig	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Slope	0.37
		Slope	0.37	Seepage	1.00	Seepage	0.21
35C:							
Laidig	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Seepage	0.21
		Slope	0.04	Seepage	1.00	Gravel content	0.06
35D:							
Laidig	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Seepage	0.21
36B:							
Laidig	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Seepage	0.21
				Seepage	1.00	Gravel content	0.06
36C:							
Laidig	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Slope	0.37
		Slope	0.37	Seepage	1.00	Seepage	0.21
37C:							
Laidig	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Seepage	0.21
		Slope	0.04	Seepage	1.00	Gravel content	0.06
37D:							

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
37D:							
Laidig	90	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Seepage	0.21
37E:							
Laidig	85	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to thick cemented pan	1.00	Depth to saturated zone	1.00	Seepage	0.21
38B:							
Lehew	45	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00
						Gravel content	0.85
Gainesboro	30	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.95
		Too clayey	0.50			Too clayey	0.50
38C:							
Lehew	45	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00
		Slope	0.37	Slope	0.37	Gravel content	0.85
Gainesboro	30	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.95
		Too clayey	0.50	Slope	0.37	Too clayey	0.50
38D:							
Lehew	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00
Gainesboro	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.95

38E:

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
38E:							
Lehew	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00
Gainesboro	30	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.95
39A:							
Massanetta	90	Very limited		Very limited		Somewhat limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	0.25
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
40D:							
Massanutten	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.93
40E:							
Massanutten	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.93
41D:							
Massanutten	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.93
41E:							
Massanutten	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.93
42A:							
Maurertown	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
43B:							

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
43B:							
Moomaw	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Too clayey	0.50	Depth to saturated zone	1.00	Depth to saturated zone	0.68
						Too clayey	0.50
43C:							
Moomaw	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Too clayey	0.50	Depth to saturated zone	1.00	Depth to saturated zone	0.68
		Slope	0.37	Slope	0.37	Too clayey	0.50
44B:							
Moomaw	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Too clayey	0.50	Depth to saturated zone	1.00	Depth to saturated zone	0.68
						Too clayey	0.50
44C:							
Moomaw	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to cemented pan	1.00	Depth to cemented pan	1.00
		Too clayey	0.50	Depth to saturated zone	1.00	Depth to saturated zone	0.68
						Too clayey	0.50
45A:							
Newmarc	85	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00		
46A:							
Nomberville	80	Very limited		Somewhat limited		Not limited	
		Seepage	1.00	Flooding	0.40		
		Flooding	0.40				
47C:							
Opequon	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
		Slope	0.04	Slope	0.04	Slope	0.04
48C:							

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
48C:							
Opequon	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
		Slope	0.04	Slope	0.04	Slope	0.04
48D:							
Opequon	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
49:							
Pits	100	Not Rated		Not Rated		Not Rated	
50A:							
Purdy	80	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
51D:							
Rock outcrop	55	Not Rated		Not Rated		Not Rated	
Carbo	35	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Seepage	1.00	Too clayey	1.00
		Slope	0.96	Slope	0.96	Slope	0.96
52F:							
Rock outcrop	50	Not Rated		Not Rated		Not Rated	
Drall	25	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Slope	1.00
		Depth to bedrock	1.00	Seepage	1.00	Gravel content	1.00
		Too Sandy	1.00	Depth to bedrock	0.96	Seepage	1.00
Wallen	15	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
53C:							
Sequoia	75	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Too clayey	1.00	Slope	0.04	Too clayey	1.00
		Slope	0.04			Slope	0.04
53D:							

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
53D:							
Sequoia	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
53E:							
Sequoia	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Too clayey	1.00			Too clayey	1.00
54B:							
Timberville	80	Very limited		Very limited		Very limited	
		Flooding	1.00	Flooding	1.00	Too clayey	1.00
		Too clayey	1.00			Gravel content	0.26
55A:							
Toms	75	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	0.50			Too clayey	0.50
Maurertown	5	Very limited		Very limited		Very limited	
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Depth to saturated zone	1.00
		Too clayey	1.00			Too clayey	1.00
56B:							
Trappist	85	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00			Depth to bedrock	1.00
56C:							
Trappist	85	Very limited		Somewhat limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Too clayey	1.00
		Too clayey	1.00	Slope	0.37	Depth to bedrock	1.00
		Slope	0.37			Slope	0.37
57:							
Udorthents	80	Not Rated		Not Rated		Not Rated	
58:							
Udorthents	55	Not Rated		Not Rated		Not Rated	
Urban land	30	Not Rated		Not Rated		Not Rated	
59B:							

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
59B:							
Unison	90	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
		Seepage	1.00				
59C:							
Unison	90	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Seepage	1.00			Slope	0.37
		Slope	0.37				
60B:							
Unison	90	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
		Seepage	1.00				
		Slope	0.37				
60C:							
Unison	90	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Seepage	1.00			Slope	0.37
		Slope	0.37				
61B:							
Unison	90	Very limited		Not limited		Very limited	
		Too clayey	1.00			Too clayey	1.00
		Seepage	1.00				
		Slope	0.37				
61C:							
Unison	90	Very limited		Somewhat limited		Very limited	
		Too clayey	1.00	Slope	0.37	Too clayey	1.00
		Seepage	1.00			Slope	0.37
		Slope	0.37				
62C:							
Wallen	75	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.54
		Slope	0.37	Slope	0.37	Seepage	0.50
62D:							
Wallen	75	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.54
63C:							

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
63C:							
Wallen	80	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
		Content of large stones	0.29	Slope	0.04	Seepage	0.50
63D:							
Wallen	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
63E:							
Wallen	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
64D:							
Wallen	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
64E:							
Wallen	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
64F:							
Wallen	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
65C:							
Wallen	45	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
		Content of large stones	0.29	Slope	0.04	Seepage	0.50
Lehew	35	Very limited		Very limited		Very limited	
		Depth to bedrock	1.00	Depth to bedrock	1.00	Depth to bedrock	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00
		Slope	0.04	Slope	0.04	Gravel content	0.85

65D:

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
65D:							
Wallen	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
Lehew	35	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00
65E:							
Wallen	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
Lehew	35	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00
66E:							
Wallen	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
Lehew	35	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00
66F:							
Wallen	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	0.55
Lehew	35	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Seepage	1.00
67F:							
Weikert	80	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00			Gravel content	1.00

68D:

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
68D:							
Weikert	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00			Gravel content	1.00
Berks	40	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
68E:							
Weikert	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00			Gravel content	1.00
Berks	40	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
69D:							
Weikert	45	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00			Gravel content	1.00
Berks	35	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
69F:							
Weikert	50	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00			Gravel content	1.00
Berks	40	Very limited		Very limited		Very limited	
		Slope	1.00	Slope	1.00	Depth to bedrock	1.00
		Depth to bedrock	1.00	Depth to bedrock	1.00	Slope	1.00
		Seepage	1.00	Seepage	1.00	Gravel content	1.00
70B:							
Wolfgap	75	Very limited		Somewhat limited		Not limited	
		Seepage	1.00	Flooding	0.40		
		Flooding	0.40				

Table ENG-6. - Sanitary Facilities - Continued

Shenandoah County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Trench Sanitary Landfill		Area Sanitary Landfill		Daily Cover for Landfill	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
71D: Zepp	75	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Gravel content Seepage	1.00 0.93 0.50
71E: Zepp	75	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Gravel content Seepage	1.00 0.93 0.50
72E: Zepp	80	Very limited Slope Seepage	1.00 1.00	Very limited Slope Seepage	1.00 1.00	Very limited Slope Gravel content Seepage	1.00 0.93 0.50
W: Water	100	Not Rated		Not Rated		Not Rated	